



## Adhesion to metal when using UZIN primer: PE 414 or PE 460

	UZIN PE 414 Turbo	UZIN PE 460
		
Aluminum	0	-
Copper	+	-
Brass	+	+
Stainless steel	+	+
Hot-dipgalvanized steel	0	-
Steel	+	0
Lead	+	+

Key:

- + Good adhesion
- 0 Adhesion o.k. – Individual case to be tested
- Poor adhesion

The subfloor must be structurally sound, solid, dry, clean and free of all contaminants such as grease, oil, paint, wax, sealing compounds that would impair adhesion.

No direct bonding to the metal substrates, always use one of the above mentioned UZIN products as primer.